

MARYLAND VEHICLE INSPECTION REPORT

Inspection Date: 03/10/2026
 Station Name: RIDESHARE INSPECTIONS
 5239 MORRIS ROAD
 BALTIMORE, MD 21227

Result: PASS
 Inspector: CALVIN WARREN
 Station Number: 6418
 Work Order Number: 2864
 Vehicle Class: A

Vehicle: 2022 TOYOTA CAMRY
 VIN: 151H31AKB2U57856
 Customer Name: SAMPLE CLIENT
 Phone: 410-111-XXXX
 Address: 400 EAST WEST BLVD, BALTIMORE, MD 21226

Initial Odometer: 42,715
 Ending Odometer: 42,718
 Cert. #: E2471803
 Cert Date: 03/10/2026

ROAD TEST			BRAKES			MIRRORS			DRIVER'S SEAT		
Alignment Test Drive:	X		Hydraulic System:	X		Interior:	X		Driver's Seat:	X	
Service Brake Performance:	X		Drums/Discs:	X		Exterior:	X		Comments:		
Comments:			Linings/Pads:	X		Comments:					
			Mechanical Linkage:	X							
			Booster System:	X							
			Parking Brake:	X							
STEERING			DRUMS/DISCS - LF SPEC:			FENDERS			SAFETY BELTS		
Steering Wheel:	X		Drums/Discs - LF Reading:	0.305		Left Front:	X		Safety Belts:	X	
Column:	X		Drums/Discs - RF Spec:	0.00		Right Front:	X		Comments:		
Steering Coupling:	X		Drums/Discs - RF Reading:	0.00		Left Rear:	X				
Lash:	X		Drums/Discs - LR Spec:	0.920		Right Rear:	X				
Travel:	X		Drums/Discs - LR Reading:	0.00		Comments:					
Linkage:	X		Drums/Discs - RR Spec:	0.425							
Rack and Pinion:	X		Drums/Discs - RR Reading:	0.315		WIPERS			MOTOR MOUNTS		
Steering Box:	X		Linings/Pads - LF:	10/10		Arms/Blades:	X		Engine Mounts:	X	
Power Steering:	X		Linings/Pads - RF:	0.00		Park Position:	X		Comments:		
Comments:			Linings/Pads - LR:	0.00		Controls:	X				
			Linings/Pads - RR:	12/12		Comments:					
			Comments:						UNIVERSAL AND CV JOINTS		
ALIGNMENT			FUEL SYSTEM			GLAZING			EMISSIONS		
Rear Wheel Alignment:	X		Tank:	X		Driver Door Window Mechanism:	X		Catalytic Converter:	X	
Comments:			Cap:	X		Windshield:	X		Fuel Filler:	X	
			Tubing:	X		Windows:	X		Positive Crankcase:	X	
SUSPENSION			Accelerator/Choke/Throttle:	X		Tint - Left Front Window:	N/A		Air Injection:	N/A	
Ball Joints/King Pins:	X		Comments:			Tint - Right Front Window:	N/A		Gas Recirculation:	N/A	
Wheel Bearings:	X					Tint - Left Rear Side Glass:	N/A		Evaporative Emissions:	X	
Springs and Torsion Bars:	X					Tint - Right Rear Side Glass:	N/A		Comments:		
Shock Absorbers/Struts:	X					Tint - Rear Glass:	N/A				
Ball Joints/King Pins - LU:	0.00		LIGHTING			Comments:					
Ball Joints/King Pins - LL:	0.00		Turn Signals & Self Cancel:	X		HOOD AND DOORS			ADDITIONAL COMMENTS		
Ball Joints/King Pins - RU:	0.00		Back Up:	X		Hood/Catches:	X				
Ball Joints/King Pins - RL:	0.00		Hazard:	X		Door Handles/Latches:	X				
Comments:			Brake Warning:	X		Comments:					
			Indicator Lamps:	X		FLOOR AND TRUNK PANS					
			Stop:	X		Floor:	X				
EXHAUST SYSTEM			Tail:	X		Trunk:	X				
Muffler:	X		Park:	X		Comments:					
Any Piping:	X		Side Marker:	X		SPEEDOMETER/ODOMETER					
Manifold:	X		Reflectors:	X		Speedometer:	X				
Comments:			Tag:	X		Odometer:	X				
			Dash:	X		Comments:					
			Clearance:	N/A		GEAR SHIFT					
			ID Lamp:	N/A		Auto. Trans. Gear Shift Indicator:	X				
BUMPERS			Headlamps:	X		Comments:					
Front:	X		Adjusters:	X		WHEELS AND TIRES			ELECTRICAL SYSTEM		
Rear:	X		Fog/AUX Height/Aim:	X		Left Front:	X		Horn:	X	
Comments:			Comments:			Right Front:	X		Switches/Wiring:	X	
						Left Rear:	X		Auto. Trans. Neut. Safety Switches:	X	
						Right Rear:	X		Battery:	X	
						Comments:			Connections:	X	
									Comments:		

RE-INSPECTION OF DEFECTS ONLY IF RETURNED WITHIN 30 DAYS AND WITHIN 1,000 MILE AND A PRORATED INSPECTION FEE MAY BE CHARGED. APPOINTMENTS FOR RE-INSPECTION MUST BE MADE AT LEAST 3 WORKING DAYS IN ADVANCE. P = PASSED F = FAILED R = REPAIRED